

Cyfast TC Quick drying

Cy Fast - TC

Product Descriptions: - This is finish paint based on Quick drying alkyd resin.

Intended Uses: - Can be used for wide variety of application where economy is

required as well as fast drying is required. This can be used as

maintenance finish also.

Product Information: -Colours Wide range of colours

Finish/Sheen Gloss / Matt

Volume Solids $39\% \pm 5\%$ (May Vary as per shade)

Mix Ratio Not applicable

Typical Film Thickness 30 microns dry

Theoretical Coverage 10 (m²/lt) at 30 microns dft, allow

appropriate loss factors

Method of Application Spray, Brush, Roller

Dying Information: - 30 °C

Touch dry: - 10 minute

Tack Free: - 2 Hours

Hard Dry: - Over night

Pot Life: - Not applicable



Cyfast TC Quick drying

Direction for use

- 1. Ensure the surface to be painted is free from any loose paint, dust or grease.
- 2. Stir well the paint thoroughly in the container.
- 3. Adjust the viscosity 20-22 Sec. Mix the thinner with paint as per recommended ratio (i.e.; 25% by volume) for spraying.
- 4. Stain the paint with boalting nylon no. 12.
- 5. Apply two coats of the paint **on primed** surface.
- 6. Keep the pressure to 2.8 3.5 kg / sq. cm. & air should be completely dry and free from moisture.

Warning: -

Flammable liquid and vapor Cause: - Eye irritation May cause skin irritation

First aid: -

- 1. For Eyes: 1. Immediately flush with plenty water
 - 2. Get medical attention
 - 3. Remove affected cloths
- 2. On Skin: 1. Immediately flush with plenty of water
 - 2. Remove contaminated clothing.
 - 3. Wash clothing before using.

Handling: -

Keep away from heat, sparks and flame. Avoid contact with eyes, skin and clothing

Storage: -

Keep in a cool, dry and ventilated place. Stable under normal condition.

-

Precautions: -

Do not add any thinner or material in paint, which is not recommended